



Samsung Instinct® s30™ (SPH-M810)

Carrier: Sprint

Software tested: ES.M810 CB23

How to find the software version: On the Home screen Touch **Main → Settings → General → Phone Information**

Note: **BMW makes no guarantees or warranties as to the performance of each phone while connected to your BMW via Bluetooth® Wireless Technology. Furthermore, software releases by BMW, the phone supplier or the wireless carrier dated after testing might alter compatibility results.**

Vehicles compatible:

1 Series
3 Series
5 Series
6 Series
7 Series
7 Series
X5
X6
Z4

Produced after


September 2005
September 2005
September 2005
September 2005
March 2007 to September 2008
November 2008
October 2005
October 2007
March 2009

Pairing Instructions:

1. Set vehicle in pairing mode. For details please see the vehicle user's manual.
2.
 - To turn Bluetooth on at handset: On the Home screen touch Main → Settings → Bluetooth → On
 - To search for Bluetooth devices: On the Home screen touch Main → Settings → Bluetooth → Trusted Device → +
 - Your phone will display a list of any Bluetooth device(s) that it discovers in range and available to be paired. Select the name of the Bluetooth enabled device (e.g. BMWxxxxx) with which you are pairing and press Select. Please note that the Bluetooth enabled device name may first appear as "Handsfree".
3. Type in a passkey on the handset first (on some BMW models, the passkey that is required for this step is fixed. See the car manual for the passkey. On all other cars the passkey can be selected by the user).



4. The Confirm Passkey dialog appears on the display of the car:



Repeat the passkey that was used on the handset to authenticate the handset and press Confirm passkey.

Limitations:

1. **@-Symbol Character**
On phonebook entries containing the @-symbol the @-symbol and following characters may not be visible to the car.
2. **Limited Call Transfer**
If during an Active Call Bluetooth is turned off (or device is has been taken out of range) and user turns on Bluetooth again (or re-enters range) the active call may not transfer automatically back to car. Then the call cannot be transferred manually back to car.
3. **Wrong Screen after pairing procedure**
After entering the passkey at car a Screen "Pairing failed" may appears at phone's display. Please ignore this screen, your phone will connect after a few seconds, on car's display the phones Bluetooth name will appear on a status.
4. **Call Waiting is not completely supported**