



LG VX10K Voyager

Carrier: Verizon Wireless

Software tested: VX10KV03

How to find the software version: On the Home screen touch **Menu → Settings & Tools → 9. Phone Info → SW/HW version**

Note: **BMW makes no guarantees or warranties as to the performance of each phone while connected to your BMW via Bluetooth® Wireless Technology. Furthermore, software releases by BMW, the phone supplier or the wireless carrier dated after testing might alter compatibility results.**

Vehicles compatible:

1 Series
3 Series
5 Series
6 Series
7 Series
7 Series
X3
X5
X6
Z4

Produced after


September 2006
September 2006
September 2006
September 2006
September 2006 to September 2008
November 2008
September 2006
October 2006
April 2008
March 2009

Pairing Instructions:

1. Set vehicle in pairing mode. For details please see the vehicle user's manual.
2.
 - To turn Bluetooth on at handset: On the Home screen touch Menu → Settings and Tools → Bluetooth Menu → Turn On
 - To search for Bluetooth devices: On the Home screen touch Menu → Settings & Tools → 3. Bluetooth Menu → Add New Device to start searching for Bluetooth devices. Note: "Auto pair" has to be turn off.
 - Your phone will display a list of any Bluetooth device(s) that it discovers in range and available to be paired. Select the name of the Bluetooth enabled device (e.g. BMWxxxx) with which you are pairing and press Select. Please note that the Bluetooth enabled device name may first appear as "Handsfree".
3. Type in a passkey on the handset first (on some BMW models, the passkey that is required for this step is fixed. See the car manual for the passkey. On all other cars the passkey can be selected by the user).



4. The Confirm Passkey dialog appears on the display of the car:



Repeat the passkey that was used on the handset to authenticate the handset and press Confirm passkey.

5. Select YES if the device requests permission to bond with the phone. Please note: Sometimes the Bluetooth Phone will display for a few seconds that the “connection failed”. If the same passkey was entered on BMW and Bluetooth Phone, the message will disappear after few seconds and the phone will connect properly to BMW, displaying “connection successful”.

Limitations:

1. **Call Waiting is not completely supported**